

Complete Laboratory Solutions [Tel] 091 574355 [Fax] 091 574356 [Email] services@cls.ie [web] www.cls.ie

CERTIFICATE OF ANALYSIS

Client: Michael J. Murphy

Kiltiernan Group Water Scheme

Caheradoo Kilcolgan Co. Galway Report No.
Date of Receipt
Start Date of Analysis
Date of Report

17/06/2020 18/06/2020 23/06/2020

418797

Order Number

Sample taken by : Client

Lab No	Sample Description	Test		Result	Units
1056545	Kiltiernan GWS. Water Sample 1	E coli (Filtration) (Environmental Waters)	I, R	0	cfu/100ml
		Total Coliforms (Filtration) (Environmental Waters)	I, R	0	cfu/100ml



Approved by:

- Owe Wirke

Louise Quirke Reporting Technician

See below for test specifications and accreditation status.

This report only relates to items tested and shall not be reproduced but in full with the permission of CLS.

Ocfu is reported in waters, this refers to 'not detected in volume tested'

It is recommended that water samples requiring microbiological analysis should be tested within 24 hours of sampling.CLS will test food, water and swabs samples within 24 hours of receipt.

Where samples have been taken by the Client, results apply to the samples as received.



Complete Laboratory Solutions [Tel] 091 574355 [Fax] 091 574356 [Email] services@cls.ie [web] www.cls.ie

In-House Test	Specification	17025	GMP/FDA*	ISO**
E coli (Filtration) (Environmental Waters)	CLS 16	Yes	No	Yes
Total Coliforms (Filtration) (Environmental Waters)	CLS 16	Yes	No	Yes

^{*}Analysis carried out in a GMP approved, FDA inspected facility (MedPharma site only).
**Laboratory Analysis, Sampling, Food Safety Monitoring and Analysts on Contract are all ISO 9001 certified.

Lab No 1056545	Sample ID Kiltiernan GWS. Water Sample 1	Sample Condition on Receipt Good condition	Sampling Date Not Supplied by Clien
1056545	Kiltiernan GWS. Water Sample 1	Good condition	Not Supplied by Clien
			J
			8
			84.
		And the second second	
		A CONTRACTOR OF THE PARTY OF TH	
		Mahk (ii) II	
			Marin 1998 /
			1000000
			(1998) (
		A 11 J. (B) (V	10000 /
			1000
			800 mg
		ACMON	
			107//
		8878 7 888888	W ////
		(1) (1) (1) (1) (1)	8)///
		3160000000	
	1		
		A STATE OF THE STA	
		1331 1132 113	

Page 2 of 2 of Report 418797

Complete Laboratory Solutions, Ros Muc, Connemara, Co. Galway

Complete Laboratory Solutions, MedPharma Division, Unit 3a, Small Business Park, Mervue, Galway